



1.玄関




1.玄関



1.玄関



1.玄関



2.靴箱



3.キッチン



3.キッチン



3.キッチン



3.キッチン



3.キッチン



水栓後ろジョーキング部分カビ落ちません

3.キッチン



3.キッチン



3.キッチン



3.キッチン



4.トイレ



4.トイレ



4.トイレ



4.トイレ



4.トイレ



4.トイレ



5.洗面所



5.洗面所



5.洗面所



6.乾燥機



7.脱衣所



8.洗濯機防水パン



9.浴室



9.浴室



9.浴室



9.浴室



9.浴室



9.浴室



9.浴室



9.浴室



10.ガラス



10.ガラス



10.ガラス



10.ガラス



10.ガラス



11.ベランダ



11.ベランダ



11.ベランダ






11.ベランダ



11.ベランダ



12.床



12.床



12.床



12.床



写真

12.床



12.床




12.床



12.床



13.照明



13.照明



14.クローゼット



14.クローゼット




14.クローゼット




16.その他



16.その他



16.その他



16.その他



17.修繕



コーナーキャップが無い

17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕




17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕




17.修繕



17.修繕



17.修繕



クレセント取替before

17.修繕



17.修繕




17.修繕



17.修繕



17.修繕



17.修繕



a f t e r



17.修繕



17.修繕



17.修繕



17.修繕



17.修繕



18.網戸張替 (after)



18.網戸張替 (after)



18.網戸張替 (after)



18.網戸張替 (after)



18.網戸張替 (after)

